



## FINDING AID: SELWYN FOLDER 26

### Collection Overview

**Identifier:** SELWYN\_F 26

**Inclusive Dates:** 1998 - 1999

**Extent:** 1

### Scope and Content

Artifact dis-assembly and storage, job number 2050. Includes memo regarding procedures for temporary removal of large cornice with brackets from site, bracket elevation and diagram, notes from Architectural Accents regarding removal of balcony cornice molding, and black and white photo reproductions of cornice and surrounding areas.

**Access Restrictions:** Consult archivist for permissions. For detailed information regarding use of this collection, please contact the Roundabout Theatre Archives at [archives@roundabouttheatre.org](mailto:archives@roundabouttheatre.org) or by calling 212-719-9393.

### Parent Collection

Selwyn Theatre Historic Renovation - Architectural 2